

## Hardware Updates

---

Link: <https://help.gpsinsight.com/device-script-updates-4-23-2021/> Last Updated: April 23rd, 2021

The following device scripts have been updated with new features.

### GPSI-5000

- 5000 (Diag) LD/HD/U (PEG Enable) (470) v4.6
- 5000 (HW) LD/HD/U (PEG Enable) (470) v4.6
  - Added ability to send DTC report when MIL lamp turns on
  - Updated realtime reporting functionality to reduce data usage
  - Added ability to send vehicle ID report with heartbeats
  - Updated default GPS sleep timer from 30 minutes to 5 minutes (ASK-1592)
  - Updated default Bluetooth setting to BLE Keyfob (was ELD Flex)



**Note.** Please coordinate with our Support team to have your devices updated.

### PNP-3100

- PNP - 4532-4562 (84a/.82/.43) v6.0.8 (435)
  - Updated default Bluetooth setting to BLE Keyfob
  - Resolved issue where Driver ID buzzer failed to buzz a full 30 minutes if the driver fails to press the BLE Keyfob driver assign button
  - Resolved issue where BLE Keyfob driver assignment will not send unless vehicle is Ignition On (ASK-1644)



**Note.** Please coordinate with our Support team to have your devices updated.