

## ELD Updates

---

Link: <https://help.gpsinsight.com/eld-flex-release-3-19-2021/> Last Updated: March 19th, 2021

This Release Notes announcement is for ELD Flex iOS and Android users.

### Android

- Enabling State of Emergency or Short Haul exceptions will no longer cause the clock to indicate the driver has millions of hours of available time.
- The split sleeper check has been corrected to properly recognize unique edge cases.
- Corrected an issue where changing vehicles would not actually change the vehicle in the user's data, but would indicate a change in the user interface. This also corrects an issue where the VBUS connection symbol may not appear on a driver's application.
- Fixed VBUS connection issues resulting in 'VBUS Not Configured' or 'VBUS Error' dialogs.
- Drivers will no longer have issues automatically connecting to vehicles.

### iOS

Established parity between Android and iOS enumerations. This corrects a number of known issues:

- Switching to vehicles on Android that were previously driven on will no longer display 'VBUS not configured' or 'VBUS Error' dialogs
- VBUS device types will no longer appear blank in the edit Equipment dialog after a vehicle is accessed by a driver using an iOS device
- VBUS configurations will no longer be affected by iOS access.
- Added expected available hours & cycle information to the Canadian Operating Zone Change prompt.