

Link: <https://help.gpsinsight.com/hardware-update-10-27-2022/> Last Updated: October 27th, 2022

This Product Release Notes announcement includes notification of hardware updates.

Hardware

AT-3000 - New Temperature Sensor Configuration

A new add-on configuration is now available for **AT-3000 devices** with temperature sensors attached, offering the option to alert users if/when the temperature sensor reaches 50°F or greater.



Note. Please coordinate with the Support team to update your devices.