Hardware Update 5/6/2022



Link: https://help.gpsinsight.com/hardware-update-5-6-2022/ Last Updated: May 6th, 2022

This Release Notes announcement highlights new hardware updates.

NEW Add-on Configuration – GPSI-3900s and GPSI-4000s

A new add-on configuration is now available for GPSI-3900s and GPSI-4000s where users can be alerted if/when the device reads an external voltage threshold of 11 volts.



Note. Please coordinate with our Support team to have your devices updated.

Magellan SmartFleet Map Update

A new Magellan map update is now available for download, including:

SmartFleet Navigation APP v159

Fixed system brightness issue – Set system brightness to the lowest level. Start navigation APP. System brightness automatically changes to the maximum level.

• Map v86

New map update



Note. Please coordinate with our Support team to have your tablets updated.