Release Notes 9/05/2023



Link: https://help.gpsinsight.com/release-notes-9-05-2023/ Last Updated: June 20th, 2023

This Product Release Notes announcement includes an introduction to GPS Insight DVIR.

New Product Offering

GPS Insight DVIR - Now Available

GPS Insight DVIR (iOS and Android compatible) offers an FMCSA/NSC compliant (US/Canada) DVIR solution designed to electronically record DVIRs and DVIR-related processes completed by admins/managers, drivers, and mechanics.

TANGPS E Lids @fildDoc / Account Preferences					ticle Inspection Form Manager			(3:27 📕 ගි ම 🔌 🕶 ⊿ 044 Vehicle Inspection	
Inspection Forms					Inspection F				
Inspection History	Vehicle:	* Al		late Range: This Month w € 03	1-0001	Defect Status:		Equipment Setup	8 9
	Vitor		Impedian Number Defects		Impection Type	Created By	Coulor1		
	> _ ===			Condition Unsafe		adureQVIR2	2125-15-1	TYPE *	~
	> 101			Condition Disaded	. Ad Hot	adureleaformoriy	212-13-1	EQUIPMENT *	
					Pie1g	adureQVR2	2123-13-1	Vehicle	~
	Part	2 - Schedules		ł	. Polg	adureQVR2	2125-13-1	VEHICLE * Sharon Geometris	~
Schedule 1 – Truck, Tractor & Trailer					Postta	adureQVIR2	2123-13-1	FORM *	-
Application: This schedule applies gross vehicle weight o	to trucks, tractors and to of 4500 kg.	railers or combinations th	ereof exceeding a regin	stered	t. Pella	adureQVIR2	2125-13-1	Schedule 1 - Truck, Tractor	~
 I. Air Brude System Deforeto; Audible air leak. Slow air pressure built 	ð-up náz.	Major Defect(s) • Pusheod stroke of any b • Air loss rate exceeds po • Inoperative towing vehi • Low air warning system	escribed limit. cle (tractor) protection sy fails or system is activat	vitem.	L Pala	adumD/H2	212-0-4	ODOMETER 100 km HOUR METER	
2. Cab Defectiti • Occepant compartment 3. Cargo Socurrement Defectiti	nt door fails to open.	Inoperative service, part Major Deficit(s) Any cab or alonger door Major Deficit(s)							
 Insecure or improper load covering (<u>e.g. wrong</u> type or flapping in the wind). 		 Insecure cargo. Absence, failure, malifa securement device or lo 		required cargo					
4. Coupling Devices									
Defect(s) Major Defect(s) • Coupler or mounting has loose or missing • Coupler is inscenze or movement exceeds prescribed limit. fantener. • Coupler or locking mechanism is damaged or fails to lock. • Defective, incorrect or missing safety chain/cable.			alls to lock.						
5. Dangeroux Goods		Major Defectiv)							
		Dangerous goods requir	ements not met.	I					
 Deliver Cantrols Defivitio Accelerator pedal, cluvisual indicators or in properly. 	nch, gauges, audible and struments fail to function								
 7. Defection Defection Seat is damaged or fair position. 	lls to remain in set	Major Defect(s) • Seatbelt or tether belt is	insecure, missing or malt	functions.	1963				
A. Electric Brake System Defocitie • Loose or insecure wire connection.		Major Defect(s) • Inoperative breakaway • Inoperative brake.	Arvice.					Back Nex	t

For additional information, please see About GPS Insight DVIR.